ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0637, W0763, W0769, W0767	NA	Canara bank layout balance roads
Segment No.	**Total Length (m)**	
9/C-W0637/S114539	253.31	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	169.92	77.578596	13.067866	77.578049	13.066427	W0767	DEAD END
2	62.36	77.578422	13.068243	77.578764	13.067790	W0655	DEAD END
3	21.03	77.578222	13.068545	77.578327	13.068385	W0763	W0655

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to roads at Canara bank layout balance roads in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	1500000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements and Asphalting to roads at Canara bank layout balance roads in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	009-15-000003
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/ BBMP/E-PMT/WO/318/2014-15	23/02/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/01/2016	29/01/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M SRIVIVASA MURTHY		0.00

Phone No.	E-Mail ID
9845132243	

Field Inspection Details

Number of Trees	Any Other Information	Name
16		SURESH
Date of Inspection	**Remarks**	
25/03/2017	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone:	YELAHANKA	Ward No:	9	Ward Name:	Vidyaranyapura	Street ID:	W0637, W0763, W0769, W0767

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	25/03/2017	24/04/2017	COMPLETED
SE	VASU K M	25/03/2017	24/04/2017	COMPLETED
EE	YARAPPA REDDY	25/03/2017	24/04/2017	COMPLETED
AEE	SHIVAKUMAR	25/03/2017	24/04/2017	COMPLETED
AE	SURESH	25/03/2017	24/04/2017	COMPLETED
AE	SURESH	25/03/2017	24/04/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0637, W0763, W0769, W0767